



handspring
Handsprint, Inc.
189 Bernardo Ave.
Mountain View, CA 94043

July 7, 2003

Federal Communications Commission
Office of Engineering and Technology
Equipment Authorization Division
7345 Oakland Mills Road
Columbia, Maryland 21046

Subject: Tune Up procedure for the CDMA Treo 600

Gentlemen,

The CDMA RF module within the Treo 600 CDMA version is simply a purchased component. The module is calibrated and adjusted at the manufacturers facility. The calibration / tune up procedure is a confidential document of the manufacturer of the module.

Handspring does not perform any additional calibration or adjustments to the module after it is delivered to Handspring nor does Handspring have access to the calibration procedure.

If there are any questions, please do not hesitate to contact me at
dwaitt@handspring.com

Sincerely

A handwritten signature in black ink, appearing to read "David Waitt".

David Waitt
Sr. Regulatory Engineer