


File Number: BP7169  
Project Number: 01ME05266  
Model Number: LR-911

Issued: August 15, 2001

FCC ID # OGSLR911



**Antenna Connection**

File Number: BP7169  
Project Number: 01ME05266  
Model Number: LR-911

Issued: August 15, 2001

FCC ID # OGSLR911




**LR-911 Top View**

File Number: BP7169  
Project Number: 01ME05266  
Model Number: LR-911

Issued: August 15, 2001

FCC ID # OGSLR911




**LR-911 PC Board Bottom View**



File Number: BP7169  
Project Number: 01ME05266  
Model Number: LR-911

Issued: August 15, 2001

FCC ID # OGSLR911




**LR-911 Patch Antenna**

File Number: BP7169  
Project Number: 01ME05266  
Model Number: LR-911

Issued: August 15, 2001

FCC ID # OGSLR911




**LR-911 Opened Back View**

File Number: BP7169  
Project Number: 01ME05266  
Model Number: LR-911

Issued: August 15, 2001

FCC ID # OGSLR911




**LR-911 Cable connection**



File Number: BP7169  
Project Number: 01ME05266  
Model Number: LR-911

Issued: August 15, 2001

FCC ID # OGSLR911




**LR-911 PC Board Top View**

File Number: BP7169  
Project Number: 01ME05266  
Model Number: LR-911

Issued: August 15, 2001

FCC ID # OGSLR911




**LR-911 without shield**



File Number: BP7169  
Project Number: 01ME05266  
Model Number: LR-911

Issued: August 15, 2001

FCC ID # OGSLR911



**LR-911 without Shield and Cover**