
## Report No.: FR551215

## Appendix C. Set up Photograph

## Conducted Emission



FRONT VIEW



**REAR VIEW** 

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C1 of C3 Issued Date : May 27, 2005






SIDE VIEW

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C2 of C3
Issued Date : May 27, 2005






## **Radiation Emission**



FRONT VIEW



**REAR VIEW** 

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C3 of C3 Issued Date : May 27, 2005