
Report No.: FR581903

Appendix C. Set up Photograph

Conducted Emission



FRONT VIEW





REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C1 of C3
Report Issued Date : Sep. 15, 2005

Rev. 01





SIDE VIEW


SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C2 of C3
Report Issued Date : Sep. 15, 2005


Rev. 01



Radiation Emission



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C3 of C3
Report Issued Date : Sep. 15, 2005

Rev. 01