Advantra America Inc. 5220 Spring Valley Road

ADVANTRA II)

Suite LL-20 Tel: (972) 759-0165 Dallas, Texas 75240 Fax: (972) 759-0174

To:

FCC Equipment Approval Services

P.O Box 358315 Pittsburgh PA 15251-5315

USA

From: Phil Tyler

Advantra America Inc.

24 May 99

Sir/ Madam:

This application is to register a change of company ownership, due to sale of the paging line of business, from Philips Consumer Communications PLC to Advantra U.K. Ltd. This affects the products listed below, but please note we shall be using our U.S. office as the applicant, as shown on form 731. -

List of affected products, as per : -

2.933 part (a), application for equipment authorisation due to change in FCC ID without a change in design, circuitry or construction.

2.933 part (b)(1) and (2);

ORIGINAL FCC ID (1)	Date of grant (2)	Frequency range MHz	NEW FCC ID
M7VMYNA900F	01/16/1998	929-932	OJ4MYNA900F
M7VMYNAUHF	07/07/1997	410-490	OJ4MYNAUHF
M7VTWOCANUHF	05/21/1997	410-490	OJ4TWOCANUHF
M7VTWOCAN900	01/30/1998	929-932	OJ4TWOCAN900
M7VKALA900F	03/09/1998	929-932	OJ4KALA900F
M7VKALANIVHF	02/23/1998	137-174	OJ4KALANIVHF
M7VKALANIUHF	02/23/1998	410-490	OJ4KALANIUHF
M7VCOBALT900	05/05/1997	929.0125-	OJ4COBALT900
M7VCOBALT900 M7VKITE900F M7VKITEVHF M7VKITEUHF	05/05/1997 03/09/1998 10/27/1997 10/27/1997	932.0125-932.0125 929-932 146-174 430-470	OJ4COBALT900 OJ4KITE900F OJ4KITEVHF

Note; 'FCC ID' incorporates the Grantee code and the Equipment Product Code.

2.933(3)	- NA
2.933(4)	- the equipment bearing the modified ID does not differ from the original equipment.
2.933(5)	- the data previously filed with the FCC continues to be representative of and applicable to the equipment bearing the change of FCC ID.
2.933(6)	- NA
2.933(7)	- Photos as per 2.1033(b)(7)
2.933(7)(c)	- NA

(NA = not applicable)

.....cont/

CONFIDENTIALITY NOTICE / ADVANTRA AMERICA INC. PROPRIETARY DATA

This message contains private and confidential information and is intended only for the use of the person named above. Unauthorised use, disclosure or copying is strictly prohibited and may be unlawful. If you have received this transmission in error, please immediately advise us by telephone so that we can arrange for the return of the document at no cost to you.

Please find enclosed form 731, payment for US\$365 payable to FCC and equipment photographs as per 2.1033(b)(7).

Thank you and best regards,