




Figure 385: Spurious Emissions at Antenna Terminal 256QAM, 1937.5MHz,
B.W. 15MHz, Sub Carrier 15 kHz




Figure 386: Spurious Emissions at Antenna Terminal 256QAM, 1962.5MHz,
B.W. 15MHz, Sub Carrier 15 kHz




Figure 387: Spurious Emissions at Antenna Terminal 256QAM, 1987.5MHz,
B.W. 15MHz, Sub Carrier 15 kHz




Figure 388: Spurious Emissions at Antenna Terminal 256QAM, 1937.5MHz,
B.W. 15MHz, Sub Carrier 30 kHz




Figure 389: Spurious Emissions at Antenna Terminal 256QAM, 1962.5MHz,
B.W. 15MHz, Sub Carrier 30 kHz




Figure 390: Spurious Emissions at Antenna Terminal 256QAM, 1987.5MHz,
B.W. 15MHz, Sub Carrier 30 kHz




Figure 391: Spurious Emissions at Antenna Terminal 256QAM, 1937.5MHz,
B.W. 15MHz, Sub Carrier 60 kHz




Figure 392: Spurious Emissions at Antenna Terminal 256QAM, 1962.5MHz,
B.W. 15MHz, Sub Carrier 60 kHz




Figure 393: Spurious Emissions at Antenna Terminal 256QAM, 1987.5MHz,
B.W. 15MHz, Sub Carrier 60 kHz




Figure 394: Spurious Emissions at Antenna Terminal 256QAM, 1940.0MHz,
B.W. 20MHz, Sub Carrier 15 kHz




Figure 395: Spurious Emissions at Antenna Terminal 256QAM, 1962.5MHz,
B.W. 20MHz, Sub Carrier 15 kHz




Figure 396: Spurious Emissions at Antenna Terminal 256QAM, 1985.0MHz,
B.W. 20MHz, Sub Carrier 15 kHz