




Figure 349: Spurious Emissions at Antenna Terminal 64QAM, 1935.0MHz,
B.W. 10MHz, Sub Carrier 60 kHz




Figure 350: Spurious Emissions at Antenna Terminal 64QAM, 1962.5MHz,
B.W. 10MHz, Sub Carrier 60 kHz




Figure 351: Spurious Emissions at Antenna Terminal 64QAM, 1990.0MHz,
B.W. 10MHz, Sub Carrier 60 kHz




Figure 352: Spurious Emissions at Antenna Terminal 64QAM, 1937.5MHz,
B.W. 15MHz, Sub Carrier 15 kHz




Figure 353: Spurious Emissions at Antenna Terminal 64QAM, 1962.5MHz,
B.W. 15MHz, Sub Carrier 15 kHz




Figure 354: Spurious Emissions at Antenna Terminal 64QAM, 1987.5MHz,
B.W. 15MHz, Sub Carrier 15 kHz




Figure 355: Spurious Emissions at Antenna Terminal 64QAM, 1937.5MHz,
B.W. 15MHz, Sub Carrier 30 kHz




Figure 356: Spurious Emissions at Antenna Terminal 64QAM, 1962.5MHz,
B.W. 15MHz, Sub Carrier 30 kHz




Figure 357: Spurious Emissions at Antenna Terminal 64QAM, 1987.5MHz,
B.W. 15MHz, Sub Carrier 30 kHz




Figure 358: Spurious Emissions at Antenna Terminal 64QAM, 1937.5MHz,
B.W. 15MHz, Sub Carrier 60 kHz




Figure 359: Spurious Emissions at Antenna Terminal 64QAM, 1962.5MHz,
B.W. 15MHz, Sub Carrier 60 kHz




Figure 360: Spurious Emissions at Antenna Terminal 64QAM, 1987.5MHz,
B.W. 15MHz, Sub Carrier 60 kHz