




Figure 361: Spurious Emissions at Antenna Terminal 64QAM, 1940.0MHz,
B.W. 20MHz, Sub Carrier 15 kHz




Figure 362: Spurious Emissions at Antenna Terminal 64QAM, 1962.5MHz,
B.W. 20MHz, Sub Carrier 15 kHz




Figure 363: Spurious Emissions at Antenna Terminal 64QAM, 1985.0MHz,
B.W. 20MHz, Sub Carrier 15 kHz




Figure 364: Spurious Emissions at Antenna Terminal 64QAM, 1940.0MHz,
B.W. 20MHz, Sub Carrier 30 kHz




Figure 365: Spurious Emissions at Antenna Terminal 64QAM, 1962.5MHz,
B.W. 20MHz, Sub Carrier 30 kHz




Figure 366: Spurious Emissions at Antenna Terminal 64QAM, 1985.0MHz,
B.W. 20MHz, Sub Carrier 30 kHz




Figure 367: Spurious Emissions at Antenna Terminal 64QAM, 1940.0MHz,
B.W. 20MHz, Sub Carrier 60 kHz




Figure 368: Spurious Emissions at Antenna Terminal 64QAM, 1962.5MHz,
B.W. 20MHz, Sub Carrier 60 kHz




Figure 369: Spurious Emissions at Antenna Terminal 64QAM, 1985.0MHz,
B.W. 20MHz, Sub Carrier 60 kHz




Figure 370: Spurious Emissions at Antenna Terminal 256QAM, 1932.5MHz,
B.W. 5MHz, Sub Carrier 15 kHz




Figure 371: Spurious Emissions at Antenna Terminal 256QAM, 1962.5MHz,
B.W. 5MHz, Sub Carrier 15 kHz




Figure 372: Spurious Emissions at Antenna Terminal 256QAM, 1992.5MHz,
B.W. 5MHz, Sub Carrier 15 kHz