



HERMON LABORATORIES

June 6, 2006

American TCB
6731 Whittier Ave
Suite C110
McLean, VA 22101
Attn: Mr. T. Johnson, Examining Engineer

RE: your e-mail dated May 30, 2006; Mobile Access Networks Ltd.
FCC ID:OJFMA2K-IDEN-SMR, ATCB003236

Dear Mr. Johnson,
Please find below the answers to your questions.

- 1) The revised Users Manual (please see page 35), file "User_guide_16224-2_rev1" was uploaded on June 6, 2006.
- 2) The file "RF_exposure_16224-2" was uploaded on June 6, 2006 via RF Exposure Info folder.
- 3) The both modulations, iDEN and SMR, were provided throughout power, conducted spurious and occupied bandwidth test. Please refer to pages 9, 30, 44 of MOBRAD_FCC.16224-2_rev1.
NB! The same pages 9, 30, 44 of MOBRAD_FCC.16224-1_rev1 show that the both modulations, iDEN and SMR, were provided for MA1000 (1K) unit.

Sincerely,

Marina Cherniavsky,
certification engineer
Hermon Laboratories