

---

## INTERTEK TESTING SERVICE

---

Report No.: 16070293HKG-001 (FCC)  
16070293HKG-002 (IC)

### Equipment Photographs

Model : 0442/0409

(Internal)



---

FCC ID: OKP0442-0449  
IC: 7091A-04420449

---

## INTERTEK TESTING SERVICE



---

Report No.: 16070293HKG-001 (FCC)  
16070293HKG-002 (IC)

### Equipment Photographs

Model : 0442/0409

(Internal)



---

FCC ID: OKP0442-0449  
IC: 7091A-04420449

---

## INTERTEK TESTING SERVICE


---

Report No.: 16070293HKG-001 (FCC)  
16070293HKG-002 (IC)

### Equipment Photographs

Model : 0442/0409

(Internal)



---

FCC ID: OKP0442-0449  
IC: 7091A-04420449

---

## INTERTEK TESTING SERVICE



---

Report No.: 16070293HKG-001 (FCC)  
16070293HKG-002 (IC)

### Equipment Photographs

Model : 0442/0409

(Internal)



---

FCC ID: OKP0442-0449  
IC: 7091A-04420449

---

## INTERTEK TESTING SERVICE


---

Report No.: 16070293HKG-001 (FCC)  
16070293HKG-002 (IC)

### Equipment Photographs

Model : 0442/0409

(Internal)



## INTERTEK TESTING SERVICE

---

Report No.: 16070293HKG-001 (FCC)  
16070293HKG-002 (IC)



---

FCC ID: OKP0442-0449  
IC: 7091A-04420449