

REFAX

MODEL: 51605A



Mar 21, 2003.

Federal Communications Commission Authorization and Evaluation Division 7435 Oakland Mills Road Columbia, MD 21046

To Whom It May Concern:

I would like to confirm you that, the vendor would add 5.6K ohm resistor between B1 and C12 locations for future production and shipment.

Best regards,

Now Wee Ltd.

Dickson Fung Senior Quality Engineer