

## Class 2 change Request

We, **Alcatel-Lucent Enterprise** hereby declare that the product and request to update the FCC and IC listing of the product: My IC Phone Handset Bluetooth® with one remove CPU and audio amplifier, This means that there are no changes made to the PCB of the listed product ,and remove cpu ,audio amplifier , that do not change the RF performance . Remove audio amplifier to decrease the receive noise. The CPU is used as a host to configure the BT module. Now the CPU is obsolete and out of order. So we have to remove it. Without CPU, the BT module works in full stack mode.

|                                    |                                |
|------------------------------------|--------------------------------|
| IP TOUCH 4068EE Handset Bluetooth® | My IC Phone Handset Bluetooth® |
| 2pin for charger                   | 4pin for charger               |

The two model : My IC Phone Handset Bluetooth® and IP TOUCH 4068EE Handset Bluetooth® are the same Product , except IP Touch 4068EE is 2pin for charger .

Product Name: My IC Phone Handset Bluetooth® ; IP TOUCH 4068EE Handset Bluetooth®

Model name: My IC Phone Handset Bluetooth® ; IP TOUCH 4068EE Handset Bluetooth®

Brand name: Alcatel-Lucent

FCC ID: OL3OT8HSBT

IC number: 1737D-OT8HSBT

(Name of product, type or model, batch or serial number)

### Hardware difference of modified as following:

- 1 The obsolete CPU AT91FR40162 ARM7TDMI in the prototype BT handset is removed.
- 2 The audio amplifier SSM2211 in the prototype BT handset is removed.

Company: Alcatel-Lucent Enterprise

Address: 1 Route du Dr A.Schweitzer 67408 ILLKIRCH (France)

### Point of contact:

(Place, date of issue)

Alcatel-Lucent Enterprise

Name : Rainier Baltz

Title:manager

Email: rainier.baltz@alcatel-lucent.com

Signature 2012-4-16

