



Brian Bhaghtalab
National Certification Lab
8370 Court Ave.
Suite B-1
Ellicott City, MD 21043

August 7, 2001

Dear Brian,

The enclosed is in response to your request for additional information.

Timing: Time from Transmission to receiver relay close with no interference: Min: 64ms, Max: 120ms

Time from Transmitting stop function to stop relay contacts break with no interference:
Min: 64ms, Max: 120ms

Time from Interference/out of range to stop relay contacts break: Min: 870ms, Max: 920ms

Additionally I have enclosed the block diagrams and other documentation you have requested. I hope this will quickly resolve the issuing of the certificate.

Regards,

A handwritten signature in black ink, appearing to read "Robert M. Coupland".

Robert M. Coupland
Managing Director

TELERADIO COMPANY
1006 CORPORATE LANE UNIT C
MURRY CORPORATE PARK
EXPORT, PA 15632

PHONE: 724-733-1200
TOLL FREE: 1-888-744-6560
FAX: 724-733-1223

<http://www.teleradiocompany.com>