

From: "Kathy Grzovic" <kgrzovic@rheintech.com>
To: "Doug Noble" <dnoble@americanTCB.com>
Subject: FW: FCC ID: ONJ-3ECJ68B3E

Hi Doug:

I have just realized that the Class II PC application recently approved had an incorrect FCC ID# in the test report and on the 731 Form (ONJ-3ECJ68B3E). The frequency and power output in the test report and on the 731 form are the characteristics of the product certified under the FCC ID# for which we intended to obtain a Class II permissive change for our client (ONJ-3ECJ68A4D).

To correct this situation, can I submit a test report and 731 Form with the correct FCC ID, and get a corrected grant issued? Will this eliminate the permissive change grant issued on 2/19/04 for ONJ-3ECJ68B3E?

I sincerely apologize for this error, and the inconvenience that it creates; I promise that it will not happen again.
Thank you very much for your assistance.

Kathy
520-877-8105