9

S


· 70= Rango.

## LOCATION OF FCCID STICKER:

R/C TURBO TWISTER / STUNT CAR MODEL NO: 0980

FCC ID: OPMHC20026002
THIS DEVICE COMPLIES WITH PART 15 OF
THE FCC RULES. OPERATION IS SUBJECT TO
THE FOLLOWING TWO CONDITIONS: (1) THIS
DEVICE MAY NOT CAUSE HARMFUL
INTERFERENCE. AND (2) THIS DEVICE MUST
ACCEPT ANY INTERFERENCE RECEIVED,
INCLUDING INTERFERENCE THAT MAY CAUSE
UNDESIRED OPERATION.

4.5 cm




## LOCATION OF FCCID STICKER:

R/C EX-1 / STUNT VEHICLE MODEL NO: 0987

FCC ID: OPMHC20026002.
THIS DEVICE COMPLIES WITH PART 15 OF
THE FCC RULES. OPERATION IS SUBJECT TO
THE FOLLOWING TWO CONDITIONS: (1) THIS
DEVICE MAY NOT CAUSE HARMFUL
INTERFERENCE. AND (2) THIS DEVICE MUST
ACCEPT ANY INTERFERENCE RECEIVED.
INCLUDING INTERFERENCE THAT MAY CAUSE
UNDESIRED OPERATION.

4.5 cm



## LOCATION OF FCCID STICKER:

R/C EX-2 / STUNT VEHICLE

MODEL NO: 0986

FCC ID: OPMHC20026002
THIS DEVICE COMPLIES WITH PART 15 OF
THE FCC RULES. OPERATION IS SUBJECT TO
THE FOLLOWING TWO CONDITIONS: (1) THIS
DEVICE MAY NOT CAUSE HARMFUL
INTERFERENCE. AND (2) THIS DEVICE MUST
ACCEPT ANY INTERFERENCE RECEIVED.
INCLUDING INTERFERENCE THAT MAY CAUSE
UNDESIRED OPERATION.

FOG ID: OPMHC20025002
THIS DEVICE COMPLIES WITH PART 16 OF
THIS PCG RULES, OPERATION IS SUBJECT TO
THE PCULOWING TWO CONDITIONS; (1) THIS
DEVICE MAY NOT CAUSE HARMFUL,
INTERESPENCE, AND (2) THIS DEVICE MUST
ACCEPT ANY INTERFERENCE RECEIVED.
INCLUDING INTERPERINCE THAT MAY CAUSE
UNDESIRED OPERATION.

1 "9V" Battery

1 "9V" Battery

Cover