

From: hliana@ccsemc.com.tw  
Sent: Wednesday, November 03  
To: Steve Cheng  
Cc: Helen Zhao; Mike Kuo; Scott Wang  
Subject: RE: GloblinkModel: GM-302, GM-303 AN03T3360

Hi Steve,

In response to your questions as followed:  
Question #1: Yes, it is plastic housing change only.  
Question #2: Refer to the attached schematic.

Please help to check the project status of CAB application for the same products ?  
It is also a urgent situation to us.  
Thank you.

Best regards,

Liana Hsiung (&#29066;&#36899;&#26525;)

=====

&#31243;&#26234;&#31185;&#25216;&#32929;&#20221;&#26377;&#38480;&#20844;&#21496;  
Compliance Certification Services Inc. (Hsintien Lab.)  
No.165, Chunghsen Road, Hsintien City, Taipei Hsien, Taiwan  
TEL:+886-2-2217-0894\*10  
FAX:+886-2-2217-1029  
hliana@ccsemc.com.tw  
=====

Steve Cheng <SCheng@CCSEMC.com>  
2003/11/02 03:26 AM

&#25910;&#20214;&#20154;&#65306; "'hliana@ccsemc.com.tw'"  
<hliana@ccsemc.com.tw>, Helen Zhao <HZhao@CCSEMC.com>  
&#21103;&#26412;&#25220;&#36865;&#65306; Mike Kuo  
<MKUO@CCSEMC.com>, Scott Wang <scotthwang@yahoo.com>  
&#20027;&#26088;&#65306; RE: ??? ??? RE: CAB Application:  
GloblinkModel: GM-302, GM-303

Hi Liana,

Subject:

Question #1: External photos shown two different housing shapes, is it plastic housing change only?

Question #2: Schematic is not readable. Please re-supply a clear copy.

Best Regards

Steve Cheng  
Compliance Certification Services  
561F Monterey Road  
Morgan Hill, CA 95037  
Tel: (408) 463-0885 x:119  
Fax: (408) 463-0888  
[scheng@ccsemc.com](mailto:scheng@ccsemc.com)  
<http://www.ccsemc.com>