


INTERTEK TESTING SERVICE

Report No.: 14061336HKG-002

Equipment Photographs

Model : 80078RX

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14061336HKG-002

Equipment Photographs

Model : 80078RX

(Internal)



FCC ID: OTA80078RX
IC: 7783A-80078RX



INTERTEK TESTING SERVICE

Report No.: 14061336HKG-002

Equipment Photographs

Model : 80078RX

(Internal)



FCC ID: OTA80078RX
IC: 7783A-80078RX



INTERTEK TESTING SERVICE

Report No.: 14061336HKG-002

Equipment Photographs

Model : 80078RX

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14061336HKG-002

Equipment Photographs

Model : 80078RX

(Internal)



FCC ID: OTA80078RX
IC: 7783A-80078RX


INTERTEK TESTING SERVICE

Report No.: 14061336HKG-002

Equipment Photographs

Model : 80078RX

(Internal)



INTERTEK TESTING SERVICE

Report No.: 14061336HKG-002

Equipment Photographs

Model : 80078RX

(Internal)

