



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

March 31, 2005

RE: Xanboo/Core Technologies

FCC ID: OU4-XWS30W

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) It can not be determined if the RF TX portion of the device is a separate daughter board mounted in the product. If so, please provide top and bottom photographs of the RF board by itself and a photograph of the main board with the RF module removed.
- 2) This device appear to normally be mounted upright. Was it also tested in this position? The device should have been configured and investigated in the configuration.
- 3) Please explain worse case duty cycle transmissions. Does only one packet get transmitted each time (i.e., one packet per 15 minutes)?

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.