

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 95 Permissive Change
OU507APFH-AP
18-0041
May 8, 2018
GE Medical Systems Information Technologies, Inc.
07APFH-AP

INTERNAL PHOTOGRAPHS




Figure 1. Main Board, Radio Side

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 95 Permissive Change
OU507APFH-AP
18-0041
May 8, 2018
GE Medical Systems Information Technologies, Inc.
07APFH-AP




Figure 2. Main Board, Component Side

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 95 Permissive Change
OU507APFH-AP
18-0041
May 8, 2018
GE Medical Systems Information Technologies, Inc.
07APFH-AP




Figure 3. RF Module, Input Side

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 95 Permissive Change
OU507APFH-AP
18-0041
May 8, 2018
GE Medical Systems Information Technologies, Inc.
07APFH-AP




Figure 4. RF Module, Output Side