



December 14, 2007

ATCB
Mr. Timothy R. Johnson

RE: GE Medical Systems Information Technologies

FCC ID: OU507APFH-AP

Mr. Johnson:

Thank you for your letter of November 20, 2007, detailing your comments regarding the above referenced application. I have included your comments in my response as reference.

1. Kindly update the test photos to remove the appropriate antenna from this application

Updated test photos have been uploaded. The photo of the small patch antenna has been removed.

2. Please update the test photographs for response to item 8 (i.e. retake or denote as appropriate).

Test photographs have been denoted because equipment is no longer available for photo re-take.

3. Please update the AC power line conducted photographs per previous item 16 (antenna should be present).

Test photographs have been denoted because equipment is no longer available for photo re-take.

4. LISN appears out of cal during the test. Please review.

The actual cal. date of the LISN was 5/10/07. A typing error was corrected in the report and the revised report was uploaded.

5. Please review sample calculation on page 24.

The sample calculation has been corrected and the revised report has been uploaded.

Please contact me with any further questions.

Sincerely,

A handwritten signature in purple ink that reads 'Sandi McEnergy'.

Sandi McEnergy
Manager