

APPENDIX 3: Photographs of test setup

Radiated Emission




Photo 1




Photo 2

Worst Case Position

ECU
 Below 30 MHz:
 X-axis

Above 30MHz:

Horizontal: X-axis / Vertical: X-axis

X-axis



Y-axis



Z-axis



FOB BOX

Below 30 MHz:

X-axis

Above 30 MHz:

Horizontal: X-axis / Vertical: X-axis

X-axis



Y-axis



Z-axis



UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Worst Case Position

LF Antenna DR

Below 30 MHz:

X-axis


Above 30 MHz:

Horizontal: X-axis / Vertical: X-axis


X-axis



Y-axis



Z-axis



Worst case position



FOB (Inserted)



FOB (Not Inserted) Worst

End of Report

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124