



AeroAntenna Technology, Inc.

an AS9100 Certified Company
20732 Lassen Street, Chatsworth, CA 91311
Phone: (818) 993-3842 Fax: (818) 993-4525

April 29, 2010

AmericanTCB
6731 Whittier Avenue
McLean VA 22101

Attn: Director of Certification

Re: Tune Up Procedure

The AMP460-1, Power Amplifier (460 MHz) does not require any tune up procedure because the amplifier has been tested by an automatic test station. As part of the test, the Maximum RF output power value has been measured. In case the RF output power is higher than specified in the acceptance test procedure, the AMP460-1 will not pass and will receive a fail status.

Sincerely

Alex Sissoev
Sr. Electronic Engineer
AeroAntenna Technology, Inc
Phone: (818) 993-3842
Fax: (818) 993-4525