

Client: M/A COM, Inc. Model: P7100<sup>(IP)</sup> UHF-L Radio Standards: FCC Part 90/IC RSS-119 Report Number: 2003046 Date: April 10, 2003


## APPENDIX J: INTERNAL PHOTOGRAPHS




PHOTOGRAPH 8: UHF-L P7100IP VIEW OF INSIDE OF FRONT COVER



PHOTOGRAPH 9: UHF-L P71001 VIEW OF TOP OF INTERFACE BOARD AND RF SHIELD




PHOTOGRAPH 10: UHF-L P7100<sup>IP</sup> VIEW OF TOP OF INTERFACE BOARD




PHOTOGRAPH 11: UHF-L P7100<sup>IP</sup> VIEW OF BOTTOM OF INTERFACE BOARD



PHOTOGRAPH 12: UHF-L P7100<sup>IP</sup> VIEW OF TOP OF RF SHIELD WITH INTERFACE BOARD REMOVED




PHOTOGRAPH 13: UHF-L P7100IP VIEW OF TOP OF MAIN BOARD WITH RF SHIELD REMOVED



PHOTOGRAPH 14: UHF-L P7100<sup>IP</sup> VIEW OF BOTTOM OF MAIN BOARD

Client: M/A COM, Inc. Model: P7100<sup>(IP)</sup> UHF-L Radio Standards: FCC Part 90/IC RSS-119 Report Number: 2003046 Date: April 10, 2003



PHOTOGRAPH 15: UHF-L P7100<sup>IP</sup> VIEW OF INSIDE WALL OF REAR CASTING WITH MAIN BOARD REMOVED