



FCC External photographs
for
47CFR15, Subpart B for Unintentional Radiators, per Section 101
Equipment authorization of unintentional radiators,
and
47CFR15, Subpart C for Intentional Radiators, per Section 247
Operation within the bands 902 to 928 MHz

on
Battery Field Service Unit (BFSU)
[FCC ID: OWS – 923]

models
Battery Field Service Unit with External Antenna
Battery Field Service Unit with Internal Antenna

report number
20050629-02-F15

manufacturer
Silver Spring Networks, Inc.
13000 West Silver Spring Drive
Butler, WI 53007

judgement
Complies as tested

tests and report by
ITC Engineering Services, Inc.
9959 Calaveras Road, P.O. Box 543
Sunol, California 94586
Tel.: (925) 862-2944
Fax: (925) 862-9013
E-Mail: docs@itcemc.com
Web Site: www.itcemc.com



Lab Code: 200172-0

EN45001 Accredited Compliance Laboratory (RES-GmbH)
Registration number: TTI-P-G 159/98-00 (RES-GmbH)

Table of Contents

PART 1 GENERAL INFORMATION..... 3
PART 2 EXTERNAL PHOTOGRAPHS..... 4

List of Figures

Figure 1: EUT Top View (with external antenna)..... 4
Figure 2: EUT Top View (with internal antenna)..... 4
Figure 3: EUT Front View..... 5
Figure 4: EUT Rear View..... 5

PART 1 GENERAL INFORMATION

Product Type Model	Battery Field Service Unit(BFSU) BFSU with External Antenna BFSU with Internal Antenna.	
Manufacturer's Name Manufacturer's Address	Silver Spring Networks Inc. 13000 West Silver Springs Drive Butler, WI 53007 United States Tel: +1 (262) 364-5317	Fax: +1 (262) 783-0205 email : juan.luglio@silverspringnetworks.com
Contact	Juan Luglio, PhD	
Test Laboratory	ITC Engineering Services, Inc. 9959 Calaveras Road, PO Box 543 Sunol, CA 94586-0543 Email: docs@itcemc.com Web Site: http://www.itcemc.com	Tel: +1(925) 862-2944 Fax: +1(925) 862-9013
Test Number and Report Numbers	20050629 – 02	20050629 – 02 – F15
Test Date(s) & Issue Date	July 08 – July 12, 2005	July 19, 2005
Test Engineer(s)	Femi Ojo and Robert Kershaw	
Chief Engineer	Michael Gbadebo, P.E	
Documentation	George Brown.	
Test Results	<input checked="" type="checkbox"/> Complies as Tested	<input type="checkbox"/> Fail

Prepared By: ITC Engineering Services, Inc.
9959 Calaveras Road, PO Box 543
Sunol, California 94586-0543
Tel: [925] 862-2944 Fax: [925] 862-9013
Email: docs@itcemc.com Web: www.itcemc.com

Product: Battery Field Service Unit (BFSU)
Models: BFSU with External Antenna
BFSU with Internal Antenna

PART 2 External Photographs.



Figure 1: EUT Top View (with external antenna)



Figure 2: EUT Top View (with internal antenna)

Prepared By: ITC Engineering Services, Inc.
9959 Calaveras Road, PO Box 543
Sunol, California 94586-0543
Tel: [925] 862-2944 Fax: [925] 862-9013
Email: docs@itcenc.com Web: www.itcenc.com

Product: Battery Field Service Unit (BFSU)
Models: BFSU with External Antenna
BFSU with Internal Antenna

FCC ID: OWS - 923



Figure 3: EUT Front View



Figure 4: EUT Rear View

Prepared By: ITC Engineering Services, Inc.
9959 Calaveras Road, PO Box 543
Sunol, California 94586-0543
Tel: [925] 862-2944 Fax: [925] 862-9013
Email: docs@itcenc.com Web: www.itcenc.com

Product: Battery Field Service Unit (BFSU)
Models: BFSU with External Antenna
BFSU with Internal Antenna