



Intertek Testing Services

ETL SEMKO

Report No.: 0215932
[Receive Mode](#)

Tested By: Ben, Report No.: 0215932


Scan Settings (1 Range)

Frequencies				Receiver Settings			
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF 60dB

Final Measurement: x QP

Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB

Transducer No.	Start	Stop	Name
21	9k	30M	EW0698





Intertek Testing Services

ETL SEMKO

Report No.: 0215932

[Receive Mode](#)

Tested By: Ben, Report No.: 0215932

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN	OFF 60dB

Final Measurement

no Results



Intertek Testing Services

ETL SEMKO

Report No.: 0215932

[Charging Mode](#)

Tested By: Ben, Report No.: 0215932


Scan Settings (1 Range)

Frequencies				Receiver Settings			
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF 60dB

Final Measurement: x QP

Meas Time: 1 s
 Subranges: 16
 Acc Margin: 20dB

Transducer No.	Start	Stop	Name
21	9k	30M	EW0698





Intertek Testing Services

ETL SEMKO

Report No.: 0215932

[Charging Mode](#)

Tested By: Ben, Report No.: 0215932

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN	OFF 60dB

Final Measurement

no Results