



Tantalus Systems Corp.
301-3480 Gilmore Way, Burnaby, BC Canada V5G 4Y1
Tel. 604.299.0458 · Fax 604.451.4111
www.tantalus.com

November 16th, 2008

To Whom It May Concern:

This letter accompanies the application for a Class II permissive change for FCC ID OZFT90002, and for a reassessment for IC 3669A-T90002

A configuration change was made to the transceiver chip. No hardware changes were made to accomplish this. The PCB, BOM and housing remains identical. The change affects certain parameters that were previously tested for FCC compliance and a test report has been submitted to support that the product remains compliant.

If there are any questions regarding this project, please do not hesitate to contact me,

Sincerely,

Mark Fairburn
RF Design Engineer
Tantalus Systems Corp.