

-----Original Message-----

From: Mario Baraona Sr. [mailto:mbaraona@atlasce.com]  
Sent: Wednesday, September 20, 2006 6:53 PM  
To: sid; gretchen@timco.cc  
Subject: Re: MAD CATZ INTERACTIVE ASIA LIMITED - FCC ID:  
P25GOMC4586B3005C

Hello Sid, Grechen;

I will answer each of the following per line item:

1. In each of the Confidentiality letters, I did name the files as I thought you wanted in reference to the upload. I will need a sample from you for clarification.
2. I understand what your request is.
3. In regards to the Controller Joypad, there really is not any flat surface large enough to accommodate the 2 part statement. The joypad front has the FCC & IC ID, the back has the on/off label. The only flat surface large enough is the battery compartment door, which is a no no. As for the Host device, since the product is a see-through device, adding a large 2 part statement will detract from the Marketable look. The Manual has the appropriate 2 part statement for each of the products.
4. On page 6 & 26 of report 0540MDC4586joypad\_subc\_rss.pdf and page 6 of report 0540MDC4586base\_subc\_rss.pdf describes the method of measurements at the three locations of the transmitter. The data I show is the worst case. If you wish to have a copy of all the data points, I will gladly provide you with the spread sheet.

If there are any other concerns, please feel free to e-mail me.

Thanks,

Mario E. Baraona Sr.

**TIMCO** ENGINEERING INC.

**TCB & FCB**

849 NW State Road 45  
Newberry, Florida 32669  
<http://www.timcoengr.com>  
888.472.2424 F 352.472.2030 email: [tei@timcoengr.com](mailto:tei@timcoengr.com)

*FCC Approvals  
Industry Canada Approvals  
Notified Body for Europe*

9/20/2006

MR. MARIO BARAONA SR.  
ATLAS COMPLIANCE & ENGINEERING, INC.  
408-971-9743 408-971-9783  
[MBARAONA@ATLASCE.COM](mailto:MBARAONA@ATLASCE.COM)

SUBJECT: MAD CATZ INTERACTIVE ASIA LIMITED - FCC ID:  
P25GOMC4586B3005C

REFERENCE: JOB 2662UC6

Dear MR. BARAONA SR.:

**This application is on hold until these questions are resolved.** Please answer all question(s) together and only respond to [tei@timcoengr.com](mailto:tei@timcoengr.com). Any other method will cause **unnecessary delay. DO NOT HIT REPLY!** Responses should also contain the Reference information, as shown at the top of this message. If acceptable response is not received within 2 week the job will be closed & there will be additional charges to reopen.

Based upon our review of this application we have the following questions:

1. Please revise your letter requesting confidentiality and list the exact files with the file extensions. I am attaching a copy of a sample for your reference as well at the FCC's Policy.
2. Once we have completed our review of this application we will up load all of the files to the FCC Website including the confidential ones and we will stop before we issue the Certification and send you the TC # so that you can view the files as they will appear on the FCC website before they become public. After you have checked them out you are to send us an email indicating that they are OKAY or telling us what is wrong. After you have confirmed everything is correct then we will issue the Certification.
3. 15.19 Two part Warning Statement: This EUT appears to be large enough that it must have the 2 part waring statement on it;

(Country of Origin)

FCC ID: \_\_\_\_\_

THIS DEVICE COMPLIES WITH PART 15 OF THE FCC RULES. OPERATION IS SUBJECT TO THE FOLLOWING TWO CONDITIONS: (1) THIS DEVICE MAY NOT CAUSE HARMFUL INTERFERENCE, AND (2) THIS DEVICE MUST ACCEPT ANY INTERFERENCE RECEIVED, INCLUDING INTERFERENCE THAT MAY CAUSE UNDESIRE OPERATION.

---

\*NOTE: If the device is too small for the 2 part warning to fit, then it must be placed in the user's manual.

4. 15.31: This rule part requires that the EUT be measured at 3 places in the band, low, middle, & High for a tuning range greater than 10MHz.

Sincerely,

Sid Sanders