

## **Response to TCB Findings**

1. Test report on Pg 4 mentions antenna connector. Please specify the type of this connector.

The antenna connector is a non-unique 2-wire press fit connector which is not accessible by the user or at the time of installation. Updated report attached.

2. How is the "lock grounding" mentioned on Pg 3 of the report for AC line conducted compliance ensured during installation? There must be warnings about this requirement in device manuals. Please specify the sections in the manuals where this has been mentioned. Otherwise the manuals must be revised to include this as a warning to the installers/users.

The lock is DC powered and a lab supply was used at the time of original testing. The noise found during this testing was related to the supply. The product was retested using a different, more quiet, lab supply and the additional grounding was not required. Updated report attached.