

T +61 2 9414 5200  
F +61 2 9415 1363  
Level 5 Keycorp Tower  
799 Pacific Highway  
Chatswood NSW 2067  
Sydney Australia  
PO Box 199 Chatswood  
NSW 2057 Australia  
[www.keycorp.net](http://www.keycorp.net)  
ABN 61 002 519 986

## TO WHOM IT MAY CONCERN TUNE-UP PROCEDURE

There is no tune-up procedure for GM48 module as fitted in K78-205

The module is fully aligned in the factory and needs no further adjustment.

By: \_\_\_\_\_



(Print Name) Ken McNulty \_\_\_\_\_

Title: Engineering Services Manager

Telephone: +61 2 9414 5200

