


Annex 3 - Internal Photographs of EUT
Mobile Payment Terminal, Model LP9100, K78-204

Photo # 1
FCC ID: P3—LP9100



Annex 3 - Internal Photographs of EUT
Mobile Payment Terminal, Model LP9100, K78-204

Photo # 2
FCC ID: P3—LP9100



**Annex 3 - Internal Photographs of EUT
Mobile Payment Terminal, Model LP9100, K78-204**

**Photo # 3
FCC ID: P3—LP9100**



Annex 3 - Internal Photographs of EUT
Mobile Payment Terminal, Model LP9100, K78-204

Photo # 4
FCC ID: P3—LP9100



Annex 3 - Internal Photographs of EUT
Mobile Payment Terminal, Model LP9100, K78-204


Photo # 5
FCC ID: P3—LP9100



Annex 3 - Internal Photographs of EUT
Mobile Payment Terminal, Model LP9100, K78-204


Photo # 6
FCC ID: P3—LP9100





Annex 3 - Internal Photographs of EUT
Mobile Payment Terminal, Model LP9100, K78-204

Photo # 10
FCC ID: P3—LP9100





Annex 3 - Internal Photographs of EUT
Mobile Payment Terminal, Model LP9100, K78-204

Photo # 12
FCC ID: P3—LP9100



WAVENET
TECHNOLOGY

Model: BOOMER II
Part #: BM211199WT54

Serial #: 000/02/341553

LLI #: 901032DE
IC: CAN 888 888 8888X
FCC ID: PQS-BM2XXXX
Wavenet Technology Pty Ltd. Made in Malaysia

In accordance with 47CFR 1.803
This device has not been authorized as
required by the rules of the Federal
Communications Commission.
This device is not, and may not be, offered
for sale or lease, or sold or leased, until
authorization is obtained.


Annex 3 - Internal Photographs of EUT
Mobile Payment Terminal, Model LP9100, K78-204

Photo # 13
FCC ID: P3—LP9100



Annex 3 - Internal Photographs of EUT
Mobile Payment Terminal, Model LP9100, K78-204

Photo # 14
FCC ID: P3—LP9100



Annex 3 - Internal Photographs of EUT
Mobile Payment Terminal, Model LP9100, K78-204

Photo # 15
FCC ID: P3—LP9100

