



November 28, 2001

FEDERAL COMMUNICATIONS COMMISSION

7435 Oakland Mills Road
Columbia, MD 21046
USA

Subject: Model Number Correction

Applicant: Keycorp Limited
Product: Mobile Payment Terminal
FCC ID: P3AK78-2XX

Dear Sir/Madam,

Please be advised that there is a correction in the model number pertaining to this application. The Model K78-202 as indicated in most of documents submitted should be K78-200. Model K78-200 is identical in every respect to K78-204 and LP9100 with the exception that it does not contain a PSTN modem. This error will affect the following documents:

- Agent Authorization
- Confidential Filing
- Certification Request
- External EUT Photos
- Internal EUT Photos
- Product Description of Mobile Payment Terminal
- Mobile Payment Terminal Test Report

If you have any queries, please do not hesitate to contact us by our TOLL FREE number:

OUR TELEPHONE NO.: 1-877-765-4173

Yours truly,

A handwritten signature in blue ink over a circular professional seal. The seal is red and contains the text "LICENSED PROFESSIONAL ENGINEER" around the top edge, "T.M. LUU" in the center, and "PROVINCE OF ONTARIO" around the bottom edge.

Tri Minh Luu, P. Eng.,
V.P., Engineering

TML/DH

3000 Bristol Circle,
Oakville, Ontario, Canada
L6H 6G4

Telephone (905) 829-1570
Facsimile (905) 829-8050

Website: www.ultratech-labs.com
Email: vhk.ultratech@sympatico.ca