

Electromagnetic Devices for Radio Communications Systems

25th day of July, 2019

TIMCO ENGINEERING INC. 849 NW State Road 45 Newberry, FL 32669 USA

FCC ID: P3TDH737

Product Name: DH737

Warning Label Attestation

Warning label messages and Class A/B disclosure will be also shown in online and point-of-sale marketing materials and on outside packaging of device.

Part 90 Signal Boosters

THIS IS A 90.219 CLASS A DEVICE

WARNING. This is NOT a CONSUMER device. It is designed for installation by FCC LICENSEES and QUALIFIED INSTALLERS. You MUST have an FCC LICENSE or express consent of an FCC Licensee to operate this device. You MUST register Class B signal boosters (as defined in 47 CFR 90.219) online at

www.fcc.gov/signal-boosters/registration. Unauthorized use may result in significant forfeiture penalties, including penalties in excess of \$100,000 for each continuing violation.

Dated this 25th day of June 2019

By:

Signature

Ricardo de Goycoechea

Printed

Title: CEO

On behalf of: Fiplex Communications, Inc.

Telephone: +1 305 884 8991