

From: Eva Kao [eva_kao@cclab.com.tw]
Sent: Thursday, November 28, 2002 5:59 PM
To: Mike Kuo
Cc: Vincent
Subject: Fw: ARESON Technology Corp., FCC ID:P5AB56, AN02T2404

Resend

----- Original Message -----

From: "Eva Kao" <eva_kao@cclab.com.tw>
To: "Mike Kuo" <MKUO@CCSEMC.com>
Sent: Friday, November 22, 2002 7:11 PM
Subject: Re: ARESON Technology Corp., FCC ID:P5AB56, AN02T2404

> Hi Mike,
>
> Answer #1: Please find the attached is revised test report.
>
> Answer #2: Please find the attachment are External and Internal photos to
> added DC connector.
>
> Thanks a lot.
> Eva
>
>

> ----- Original Message -----

> From: "Mike Kuo" <MKUO@CCSEMC.com>
> To: "Eva Kao (E-mail)" <eva_kao@cclab.com.tw>
> Sent: Friday, November 22, 2002 9:41 AM
> Subject: FW: ARESON Technology Corp., FCC ID:P5AB56, AN02T2404
>
>

> > -----Original Message-----

> > From: CERTADM
> > Sent: Thursday, November 21, 2002 5:41 PM
> > To: 'mkuo@ccsemc.com'
> > Subject: ARESON Technology Corp., FCC ID:P5AB56, AN02T2404
> >
> >

> > Notice_content

> > -----

> > Question #1: Page 7 of test report listed the FCC ID number does not
agree

> > with filing. Please make necessary change.

> >

> > Question #2: the DC connector can not be located on the internal photos.

> > Please provide additional photos to show where is DC connector on the

Eut

> to

> > enable battery charge.

> >

> > Best Regards

> >

> > Mike Kuo

> > The items indicated above must be submitted before processing can

continue

> > on the above referenced application. Failure to provide the requested
> > information within 60 days of the original e-mail date may result in
> > application dismissal and forfeiture of the filing fee. Also, please
note
> > that partial responses increase processing time and should not be
> submitted.
> > Any questions about the content of this correspondence should be
directed
> to
> > the e-mail address listed below the name of the sender.
>