Appendix A. Test Photos

 SPORTON International Inc.
 Page No.
 : A1 of A7

 TEL: 886-2-2696-2468
 Issued Date
 : Nov. 05, 2007

 FAX: 886-2-2696-2255
 FCC ID
 : P5T-WL54PCIE

FCC TEST REPORT Report No.: FR641717-01

1. Photographs of Conducted Emissions Test Configuration



FRONT VIEW




REAR VIEW

 SPORTON International Inc.
 Page No.
 : A2 of A7

 TEL: 886-2-2696-2468
 Issued Date
 : Nov. 05, 2007

 FAX: 886-2-2696-2255
 FCC ID
 : P5T-WL54PCIE



SIDE VIEW

 SPORTON International Inc.
 Page No.
 : A3 of A7


 TEL: 886-2-2696-2468
 Issued Date
 : Nov. 05, 2007

 FAX: 886-2-2696-2255
 FCC ID
 : P5T-WL54PCIE


FCC TEST REPORT Report No.: FR641717-01

2. Photographs of Radiated Emissions Test Configuration

Results of Radiated Emissions (Below 30MHz)



FRONT VIEW



REAR VIEW


 SPORTON International Inc.
 Page No.
 : A4 of A7

 TEL: 886-2-2696-2468
 Issued Date
 : Nov. 05, 2007


 FAX: 886-2-2696-2255
 FCC ID
 : P5T-WL54PCIE

FCC TEST REPORT

Results of Radiated Emissions (30MHz~1GHz)



FRONT VIEW




REAR VIEW


SPORTON International Inc. TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : A5 of A7
Issued Date : Nov. 05, 2007
FCC ID : P5T-WL54PCIE

FCC TEST REPORT Report No.: FR641717-01

Results for Radiated Emissions (1GHz~10th Harmonic)



FRONT VIEW




REAR VIEW

SPORTON International Inc. TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : A6 of A7
Issued Date : Nov. 05, 2007
FCC ID : P5T-WL54PCIE



NEAR VIEW



NEAR VIEW

SPORTON International Inc.TEL: 886-2-2696-2468
FAX: 886-2-2696-2255

Page No. : A7 of A7
Issued Date : Nov. 05, 2007
FCC ID : P5T-WL54PCIE