

From: Eva Kao [eva_kao@cclab.com.tw]
Sent: Tuesday, April 22, 2003 11:24 PM
To: Mike Kuo
Subject: Fw: Coby Electronics Co., Ltd. , P5UCXCD740, AN03T2772

> Hi Mike,
>
> Answer #1: Attached please find the revised FCC ID label.
>
> Answer #2: Attached please find the Schematic.
>
> Answer #2: Attached please find the modification report.
>
> Regards,
> Eva
>
>
> > Notice_content
> > -----
> > Question #1: The FCC ID label format listed the FCC ID number as
> BBBXCXCD740
> > which does not agree with the FCC ID label listed on TCB application
form.
> > Please make necessary changes.
> >
> > Question #2: Schematic diagram can not be read. Please provide a clear
> copy
> > of schematic diagram.
> >
> > Question #3: Special accessory (ferrite core on DC/DC cable) was added
> > during final compliance tests. Please provide a modification report
> signed
> > by the applicant to agree to incorporate such modification into each
unit
> > sold in the U.S..
> >
> > Best Regards
> >
> > Mike Kuo
> >
>
>