




Your Specialist in Loss Prevention

P/N : WG APS RAD-POS

S/N : 10/11 00001

INPUT : 24VAC 50/60Hz 0.5A

MFD : November 2010
Made in CHINA



1 10100 00001 2

Fuse replacement Build-in fuse
(time-delay fuse) 2mm x 6mm 0.5A

FCC ID : P9I-APS-RAD-P

THIS DEVICE COMPLIES WITH PART
15 OF THE FCC RULES. OPERATION
IS SUBJECT TO THE FOLLOWING
TWO CONDITIONS:(1) THIS DEVICE
MAY NOT CAUSE HARMFUL
INTERFERENCE, AND (2) THIS
DEVICE MUST ACCEPT ANY
INTERFERENCE RECEIVED,
INCLUDING INTERFERENCE THAT
MAY CAUSE UNDESIRED OPERATION.