

FCC ID: PANWL1205 Issued on May 31, 2004

5.5.4 Photographs of Conducted Emission Test Configuration

• The photographs show the configuration that generates the maximum emission.



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID. : PANWL1205 Page No. : 22of 47

Issued Date : May 31, 2004

Report No.: F452108



FCC ID: PANWL1205 Issued on May 31, 2004

04 Report No.: F452108



SIDE VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID. : PANWL1205 Page No. : 23of 47

Issued Date : May 31, 2004



FCC ID: PANWL1205 Issued on May 31, 2004

5.6.5 Photographs of Radiated Emission Test Configuration

• The photographs show the configuration that generates the maximum emission.



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID. : PANWL1205 Page No. : 420f 47

Report No.: F452108

Issued Date : May 31, 2004