

September 28, 2002

RE: TeLLUS Group Corp.
FCC ID: PB6-02011

Dear Timothy:

After the review of your comments, we have made some response upon your advice; they are summarized as follows:

1. The label with the corrected DoC notification is uploaded.
2. The missed portion of the data sheet of the ISL3873B is uploaded.
3. The Compliance sheet should be shown in the manual for the DoC device is uploaded.
4. By the manufacturer claims, the product shall not only be supplied to the system integrators but also for the ordinary end-user also. It should be a little bit strange if the info you mentioned have been printed in the manual from the ordinary end-user view. So we haven't added for the benefits of the end-user.
5. For the band-edge issue, please discard the part attached at the first-time, and only refer to the one we have uploaded last time. The difference found maybe made by the mistakes we took at the first-time. The materials uploads last-time is re-do and shown only the data of the EUT itself, done with my witness.

Should you have any questions or more information is needed, please don't hesitate to ask us.
Thank you.

Sincerely yours,
Eric Wong
Project Engineer
Training Research Co Ltd.