

TIMCO ENGINEERING INC.

849 NW State Road 45

Newberry, Florida 32669

<http://www.timcoengr.com>

888.472.2424 F 352.472.2030 email: tei@timcoengr.com

31 January 2001

FCC

Subject: INTELLIX CORP., LTD. / FCCID: PBE-DTA-201

To Whom It May Concern:

The test report says that the CPU used by the test to test this peripheral has a ferrite on the power cable but this is part of the original equipment for the CPU.

Sincerely,

Sid Sanders