

02/18/02

Hakan Lohmander
Precise Biometrics

In reference to FCC ID: PBKMS010040

Mr. Lohmander

Upon completion of review of the application for FCC ID: PBKMS010040, there are several issues that must be addressed before the application can be granted by ATCB.

Please address each issue below.

- 1) Upon reviewing the test report and set up photos, the systems appears to have been tested with an active rod antenna below 30 MHz. This is not in compliance with the FCC rules. Systems tested below 30 MHz require the use of a loop antenna. Please provide data using a loop antenna
- 2) The warning manual needs the correct FCC statements including the statements against unauthorized modifications.
- 3) In regards to your confidential letter, we cannot list the modification letter as part of the confidential material. Suggestions are as follows.
 - A) Add the changes to your parts list as an appendix so we can honor the request.
 - B) Provide a generic letter for the modifications listing only the locations and a reference to the confidential file.

Regards

David A. Case NCE
Examining Engineer
<mailto:dcase@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination.

Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.