



Internal ref: IRON/LET/0001/PB
FCC ID: PBKMS010114

Lund 08/28/2006

These are the changes on Precise 250MC, MS 010 114, between revisions R1B (ATCB 3286) and R2A (ATCB 3886):

<u>Action:</u>	<u>Reason for change:</u>	<u>Changes on PCB:</u>
Added components (CAD1, R12, R25, D9 and C44) and deleted old R12.	PIV certification of the product.	Yes
Added R23 and deleted R22.	Increased PCA revision.	No

The components below are mounted in different positions depending on product type, (<001>=250MC, <010>=200MC) - This is also the difference between ATCB 3285 and ATCB 3886.

Marked <001>: R50, D7, T14, R69, R70, D2, T4, R5, R42

Marked <010>: R48, D6, T13, R61, R64, D4, T8, R35, R43

Marked <0xx>: D3

Regards,
Per-Ola Olsson