


Client:	Intel Mobile Communications	Job Number:	J94122
Model:	3160SDW	T-Log Number:	T94177
Contact:	Steve Hackett	Project Manager:	Christine Krebill
Standard:	FCC Part 15, RSS-210	Project Coordinator:	-
		Class:	N/A

Test Configuration Photographs



Client:	Intel Mobile Communications	Job Number:	J94122
Model:	3160SDW	T-Log Number:	T94177
Contact:	Steve Hackett	Project Manager:	Christine Krebill
Standard:	FCC Part 15, RSS-210	Project Coordinator:	-
		Class:	N/A

Test Configuration Photographs #1




Client:	Intel Mobile Communications	Job Number:	J94122
Model:	3160SDW	T-Log Number:	T94177
Contact:	Steve Hackett	Project Manager:	Christine Krebill
Standard:	FCC Part 15, RSS-210	Project Coordinator:	-
		Class:	N/A

Test Configuration Photographs #2




Client:	Intel Mobile Communications	Job Number:	J94122
Model:	3160SDW	T-Log Number:	T94177
Contact:	Steve Hackett	Project Manager:	Christine Krebill
Standard:	FCC Part 15, RSS-210	Project Coordinator:	-
		Class:	B

Test Configuration Photograph #1



Client:	Intel Mobile Communications	Job Number:	J94122
Model:	3160SDW	T-Log Number:	T94177
Contact:	Steve Hackett	Project Manager:	Christine Krebill
Standard:	FCC Part 15, RSS-210	Project Coordinator:	-
		Class:	B

Test Configuration Photograph #1  
(Conducted Emissions - Power Port)



Client:	Intel Mobile Communications	Job Number:	J94122
Model:	3160SDW	T-Log Number:	T94177
Contact:	Steve Hackett	Project Manager:	Christine Krebill
Standard:	FCC Part 15, RSS-210	Project Coordinator:	-
		Class:	B

Test Configuration Photograph #2  
(Conducted Emissions - Power Port)

