



American Telecommunications Certification Body Inc.  
6731 Whittier Ave, McLean, VA 22101

August 23, 2004

RE: FCC ID: PD9WM3B2200BG\_ATCB001611

Attention: Rick Candelas

I have a few comments on this Application. Please note that further comments may arise in response to answers provided to the questions below.

1. Please note that the data tables on pages 23 and 33 of the FCC and IC reports do not provide adequate information to determine what is being reported. For example, the first few readings do not give any information other than the corrected readings. What was the raw reading? What were the correction factors involved? What was the analyzer function (QP Peak Ave)? Please provide the missing information.

Dennis Ward

<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.