

May 12, 2003

American TCB
6731 Whittier Ave.
Suite C110
McLean, VA. 22101

RE: FCC ID: PGR2W1000W
2wire, Inc.

1. There appears to be more than sufficient room on the device to place the statement required in 15.19 (the 2- condition statement). Please provide this statement on the device. Alternately please explain how the device fits the exceptions specifically listed in 15.19(a)(5).

Responds: Please refer to page 3 of 3 of the FCC label and location documents. By zooming into the label you will see that there will be no more room on the label due to other information being place on it.

2. On page 15 of the report you show limits for 15.407. This device however is a 15.247 device. Please show information related to the operating frequency of this device.

Responds: 15.407 power limits have been removed and a new revised report has been uploaded with the changes.

3. FYI - Please note that the plots provided are not clear. Plots should be easily readable.

Responds: The new uploaded report has better viewable plots.

4. Starting on page 44 of the report you use EN55022 limits. Please note that for the restricted bands below 1GHz you must use 15.209 limits. Several restricted band measurements below 1GHz appear in your data sheets. Please correct your report to show the proper limits.

Responds: The new uploaded report has the new data showing compliance with the restricted band limits.