

Company name: Address: Airspan Networks Inc. 777 Yamato Road Suite 310 Boca Raton FL 33431 USA

FCC ID:PIDASMAX365

ProST 3.65GHz Tune up procedure

Each ProST radio has been tested by automatic test station. As part of the test, the Maximum RF output power value has been masured. In case the RF output power is higher then specified in the System Description, the ProST radio doesn't pass the test and gets Fail status. ProST boards with Fail status can not be assembled as part of final product.

Name of authorized person: Zion Levy

Position: Compliances & Testing Engineer

Date: November 11, 2009