



HERMON LABORATORIES

September 13, 2006

American TCB
6731 Whittier Ave
Suite C110
McLean, VA 22101
Attn: Mr. Timothy Johnson, Examining Engineer

RE: your e-mail dated September 10, 2006; Airspan Networks Ltd.
FCC ID: PIDASMAX58, ATCB003949

Dear Mr. Johnson,
Please find below the answers to your questions.

- 1) The photograph 9 was added, the exhibit "Internal_photos_17234_rev1" was uploaded on September 13, 2006.
- 2) The label was corrected, the file "Label_location_17234_rev1" was uploaded on September 13, 2006
- 3) The new photographs, file "External_photos_17234_rev1" was uploaded on September 13, 2006. The photographs 1, 2, 3 in "Internal_photos_17234_rev1" were changed.
- 4) The adjusted file "RF_evaluation_17234_rev1" was uploaded on September 13, 2006.
- 5) You are right, the provided schematics were not correct. New files, "Schematic_diagram_17234_rev1" and "Confidentiality_letter_17234_rev1" were uploaded on September 13, 2006.
- 6) The corrected "User_Manual_17234_rev1" was uploaded on September 13, 2006.

Thank you for your assistance and support.

Sincerely,

Marina Cherniavsky,
certification engineer
Hermon Laboratories