



FCC ID:PIDMMAX700

MicroMAX 700 MHz Tune up procedure

Each MicroMAX radio has been tested by automatic test station. As part of the test , the Maximum RF output power value has been masured. In case the RF output power is higher then specified in the System Description, the MicroMAX radio doesn't pass the test and get Fail status. MicroMAX boards with Fail status can not be assembled as part of final product.

Name of authorized person: Zion Levy
Position: Compliances & Testing Engineer

A handwritten signature in black ink, appearing to be "Zion Levy", written over a horizontal line.

Date: January 25, 2009

Airspan Networks (Israel) Ltd., Israel
Tel: +972-3-9777444 ; Fax: +972-3-9777400, www.airspan.com