

INTERTEK TESTING SERVICES


Report No.: 0420033
Model No.: B0233 (DTSC)

hp

Pursuant to FCC Part 15 Section 15.227 Emissions Requirement MKR 1.0500 msec

REF .0 dBm AT 10 dB .04 dB

PEAK
LOG
10
dB/



Tested By: Kenneth Wong

Date: 30/10/04

Checked By: Ivan Wong

Date: 4/11

Test Result : Pass / Fail NA

CENTER 27.145 MHz

#RES BW 3.0 MHz

#VBW 3 MHz

SPAN 0 Hz

#SWP 30.0 msec

INTERTEK TESTING SERVICES


hp

Report No.: 0420033
Model No.: B0233 (DTSC)

Pursuant to FCC Part 15 Section 15. 227 Emissions Requirement MKR 1.0880 msec

REF .0 dBm AT 10 dB .07 dB

PEAK
LOG
10
dB/



WA SB
SC LS
CORR

Tested By: KA
(Kenneth Wong)

Date: 30/10/04

Checked By: [Signature]
(Ivan Wong)

Date: 4/11

Test Result : Pass / Fail / NA

CENTER 27.145 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 15.0 msec


Report No.: 0420033
Model No.: B0233 (DT5C)

hp

Pursuant to FCC Part 15 Section 15. 227 Emissions Requirement MKR 675.00 μ sec

REF .0 dBm AT 10 dB .64 dB

PEAK
LOG
10
dB/



WA SB
SC LS
CORR

Tested By: KA
(Kenneth Wong)

Date: 20/10/04

Checked By: [Signature]
(Ivan Wong)

Date: 2/11

Test Result : Pass / Fail / NA

CENTER 27.145 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 15.0 msec