



CMA Testing
and Certification
Laboratories
嚴爾會檢定中心

07 June 2011

Timco Engineering, Inc.

849 NW State Road 45

Newberry, Florida 32669

<http://www.timcoengr.com>

888.472.2424 F 352.472.2030 email: tei@timcoengr.com

SUBJECT: Revising FCC Label (FCC ID: PIYT9483-11A2T)

FCC ID: PIYT9483-11A2T

Applicant: Mattel Asia Pacific Sourcing Ltd.

Job No: 1104HC11

Dear Sir / Madam,

According to applicant's information, the FCC ID for permissive change application is PIYT9483-11A3T. Therefore the label photo listed on FCC Electronic Filing & Public Access System should be revised from Figure 1 to Figure 2.




Figure 1

FCC ID: PIYT9482-11A2T

The correct FCC ID should be "PIYT9483-11A2T" and the label is shown in Figure 2.




Figure 2

FCC ID: PIYT9483-11A2T

Should you have any further queries, please feel free to contact me.

Yours Faithfully,

Andrew Wong

Assistant Manager - Electrical Division

CMA Industrial Development Foundation Limited