
Subject: FW: HYUNDAI IMAGEAUEST CO., LTD., FCC ID: PJIHQP50AH000, Assessment NO.: AN04T4071, Notice#1

Dear Mike Kuo,

We always appreciate your kind cooperations on our TCB applications. We are very sorry to have kept you waiting a reply.

Answer #1: We uploaded the corrected Block Diagram on your web site.

Answer #2: As point out your Question, We checked this issue.

Then we found a mistake in User's manual. So, we re-uploaded corrected User's manual on your web site.

Please check & progress these applications.

If you have any questions or comments, please do not hesitate to contact us.

Thanks & Best regards,

Byung Ki Ham

Product Compliance Team
Hyundai Calibration & Certification Technologies Co., Ltd.

-----Original Message-----

From: Compliance Certification Services [mailto:MKuo@ccsemc.com]

Sent: Monday, July 26, 2004 5:06 PM

To: mkuo@ccsemc.com

Subject: HYUNDAI IMAGEAUEST CO., LTD., FCC ID: PJIHQP50AH000, Assessment NO.: AN04T4071, Notice#1

Question #1: The Block Diagram does not include information about local oscillator or crystal frequencies. Please provide.

Question #2: On Page 82 of the user manual it indicated that the resolution for HQP501HR can be upto 1366 x 768. However the test report shows the highest resolution during the test was only 1024 x 768. Please explain.

Best regards,
Mike Kuo

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also,

please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.